artedomus

Limestone - Natural stone slabs or tiles

Artedomus (Aust) Pty Ltd

Chemwatch: 5550-92

Version No: 2.1

Safety Data Sheet according to WHS Regulations (Hazardous Chemicals) Amendment 2020 and ADG requirements

SECTION 1 Identification of the substance / mixture and of the company / undertaking

Product Identifier

Product name	Limestone - Natural stone slabs or tiles
Chemical Name	Not Applicable
Synonyms	Not Available
Chemical formula	Not Applicable
Other means of identification	Not Available

Relevant identified uses of the substance or mixture and uses advised against

Relevant identified uses Architectural Surfaces. Use according to manufacturer's directions.

Details of the supplier of the safety data sheet

······································	
Registered company name	Artedomus (Aust) Pty Ltd
Address	6/45-55 Epsom Road Rosebery NSW 2018 Australia
Telephone	1300 278 336
Fax	Not Available
Website	www.artedomus.com
Email	info@artedomus.com

Emergency telephone number

Association / Organisation	Poisons Information Centre
Emergency telephone numbers	13 11 26 (24 hours)
Other emergency telephone numbers	Not Available

Once connected and if the message is not in your preferred language then please dial 01

SECTION 2 Hazards identification

Classification of the substance or mixture

Poisons Schedule	Not Applicable
Classification ^[1]	Skin Corrosion/Irritation Category 2, Serious Eye Damage/Eye Irritation Category 2A, Specific Target Organ Toxicity - Single Exposure (Respiratory Tract Irritation) Category 3
Legend:	1. Classified by Chernwatch; 2. Classification drawn from HCIS; 3. Classification drawn from Regulation (EU) No 1272/2008 - Annex VI

Label elements

Hazard pictogram(s)	
Signal word	Warning
Hazard statement(s)	
H315	Causes skin irritation.
H319	Causes serious eye irritation.
H335	May cause respiratory irritation.

Chemwatch Hazard Alert Code: 3

Issue Date: 22/07/2022

Print Date: 25/07/2022 S.GHS.AUS.EN

P271	Use only outdoors or in a well-ventilated area.
P261	Avoid breathing dust/fumes.
P280	Wear protective gloves, protective clothing, eye protection and face protection.
P264	Wash all exposed external body areas thoroughly after handling.

Precautionary statement(s) Response

· · · · · · · · · · · · · · · · · · ·	
P305+P351+P338	IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
P312	Call a POISON CENTER/doctor/physician/first aider/if you feel unwell.
P337+P313	If eye irritation persists: Get medical advice/attention.
P302+P352	IF ON SKIN: Wash with plenty of water and soap.
P304+P340	IF INHALED: Remove person to fresh air and keep comfortable for breathing.
P332+P313	If skin irritation occurs: Get medical advice/attention.
P362+P364	Take off contaminated clothing and wash it before reuse.

Precautionary statement(s) Storage

P405	Store locked up.
P403+P233	Store in a well-ventilated place. Keep container tightly closed.

Precautionary statement(s) Disposal

P501	Dispose of contents/container to authorised hazardous or special waste collection point in accordance with any local regulation.

Not Applicable

SECTION 3 Composition / information on ingredients

Substances

See section below for composition of Mixtures

Mixtures

CAS No	%[weight]	Name
471-34-1	>99	calcium carbonate
14808-60-7	<1	silica crystalline - quartz
Legend:	 Classified by Chemwatch; 2. Classification drav Classification drawn from C&L * EU IOELVs avail 	vn from HCIS; 3. Classification drawn from Regulation (EU) No 1272/2008 - Annex VI; 4. able

SECTION 4 First aid measures

Description of first aid measures If this product comes in contact with the eyes: Wash out immediately with fresh running water. • Ensure complete irrigation of the eye by keeping eyelids apart and away from eye and moving the eyelids by occasionally lifting the upper Eye Contact and lower lids. Seek medical attention without delay; if pain persists or recurs seek medical attention. Removal of contact lenses after an eye injury should only be undertaken by skilled personnel. If skin contact occurs: Immediately remove all contaminated clothing, including footwear. Skin Contact Flush skin and hair with running water (and soap if available). Seek medical attention in event of irritation. If fumes or combustion products are inhaled remove from contaminated area. Lay patient down. Keep warm and rested. Prostheses such as false teeth, which may block airway, should be removed, where possible, prior to initiating first aid procedures. Inhalation Apply artificial respiration if not breathing, preferably with a demand valve resuscitator, bag-valve mask device, or pocket mask as trained. Perform CPR if necessary. Transport to hospital, or doctor, without delay. Immediately give a glass of water. Ingestion First aid is not generally required. If in doubt, contact a Poisons Information Centre or a doctor.

Indication of any immediate medical attention and special treatment needed

Treat symptomatically.

SECTION 5 Firefighting measures

Extinguishing media

- There is no restriction on the type of extinguisher which may be used.
- Use extinguishing media suitable for surrounding area.

Special hazards arising from the substrate or mixture

Fire Incompatibility None known.

Continued...

Advice for firefighters		
Fire Fighting	 Alert Fire Brigade and tell them location and nature of hazard. Wear breathing apparatus plus protective gloves in the event of a fire. Prevent, by any means available, spillage from entering drains or water courses. Use fire fighting procedures suitable for surrounding area. DO NOT approach containers suspected to be hot. Cool fire exposed containers with water spray from a protected location. If safe to do so, remove containers from path of fire. Equipment should be thoroughly decontaminated after use. 	
Fire/Explosion Hazard	Decomposition may produce toxic fumes of: silicon dioxide (SiO2) May emit poisonous fumes. May emit corrosive fumes.	
HAZCHEM	Not Applicable	

SECTION 6 Accidental release measures

Personal precautions, protective equipment and emergency procedures

See section 8

Environmental precautions

See section 12

Methods and material for containment and cleaning up

Minor Spills	 Clean up waste regularly and abnormal spills immediately. Avoid breathing dust and contact with skin and eyes. Wear protective clothing, gloves, safety glasses and dust respirator. Use dry clean up procedures and avoid generating dust. Vacuum up or sweep up. NOTE: Vacuum cleaner must be fitted with an exhaust micro filter (HEPA type) (consider explosion-proof machines designed to be grounded during storage and use). Dampen with water to prevent dusting before sweeping. Place in suitable containers for disposal.
Major Spills	 Clear area of personnel and move upwind. Alert Fire Brigade and tell them location and nature of hazard. Wear full body protective clothing with breathing apparatus. Prevent, by all means available, spillage from entering drains or water courses. Consider evacuation (or protect in place). No smoking, naked lights or ignition sources. Increase ventilation. Stop leak if safe to do so. Water spray or fog may be used to disperse / absorb vapour. Contain or absorb spill with sand, earth or vermiculite. Collect recoverable product into labelled containers for recycling. Collect solid residues and seal in labelled drums for disposal. Wash area and prevent runoff into drains. After clean up operations, decontaminate and launder all protective clothing and equipment before storing and re-using. If contamination of drains or waterways occurs, advise emergency services.

Personal Protective Equipment advice is contained in Section 8 of the SDS.

SECTION 7 Handling and storage

Precautions for safe handling	
Safe handling	 Avoid all personal contact, including inhalation. Wear protective clothing when risk of exposure occurs. Use in a well-ventilated area. Prevent concentration in hollows and sumps. DO NOT enter confined spaces until atmosphere has been checked. DO NOT allow material to contact humans, exposed food or food utensils. Avoid contact with incompatible materials. When handling, DO NOT eat, drink or smoke. Keep containers securely sealed when not in use. Avoid physical damage to containers. Always wash hands with soap and water after handling. Work clothes should be laundered separately. Launder contaminated clothing before re-use. Use good occupational work practice. Observe manufacturer's storage and handling recommendations contained within this SDS. Atmosphere should be regularly checked against established exposure standards to ensure safe working conditions are maintained.
Other information	 Store in original containers. Keep containers securely sealed. Store in a cool, dry area protected from environmental extremes. Store away from incompatible materials and foodstuff containers. Protect containers against physical damage and check regularly for leaks. Observe manufacturer's storage and handling recommendations contained within this SDS. For major quantities: Consider storage in bunded areas - ensure storage areas are isolated from sources of community water (including stormwater, ground water,

 lakes and streams).
 Ensure that accidental discharge to air or water is the subject of a contingency disaster management plan; this may require consultation with local authorities.

 Conditions for safe storage, including any incompatibilities

 Suitable container

 Polyethylene or polypropylene container.
 Check all containers are clearly labelled and free from leaks.

 Storage incompatibility

 Avoid strong acids, bases.

SECTION 8 Exposure controls / personal protection

Control parameters

Occupational Exposure Limits (OEL)

INGREDIENT DATA

Source	Ingredient	Material name	TWA	STEL	Peak	Notes
Australia Exposure Standards	calcium carbonate	Calcium carbonate	10 mg/m3	Not Available	Not Available	 (a) This value is for inhalable dust containing no asbestos and < 1% crystalline silica.
Australia Exposure Standards	silica crystalline - quartz	Silica - Crystalline: Quartz (respirable dust)	0.05 mg/m3	Not Available	Not Available	Not Available
Emergency Limits						

Ingredient	TEEL-1	TEEL-2		TEEL-3	
calcium carbonate	45 mg/m3	210 mg/m3		1,300 mg/m3	
silica crystalline - quartz	0.075 mg/m3	33 mg/m3		200 mg/m3	
Ingredient	Original IDLH		Revised	IDLH	
calcium carbonate	Not Available		Not Avai	lable	
silica crystalline - quartz	25 mg/m3 / 50 mg/m3		Not Avai	lable	

Exposure controls

Expectate controlo	
Appropriate engineering controls	 Engineering controls are used to remove a hazard or place a barrier between the worker and the hazard. Well-designed engineering controls can be highly effective in protecting workers and will typically be independent of worker interactions to provide this high level of protection. The basic types of engineering controls are: Process controls which involve changing the way a job activity or process is done to reduce the risk. Enclosure and/or isolation of emission source which keeps a selected hazard "physically" away from the worker and ventilation that strategically "adds" and "removes" air in the work environment. Ventilation can remove or dilute an air contaminant if designed properly. The design of a ventilation system must match the particular process and chemical or contaminant in use. Employers may need to use multiple types of controls to prevent employee overexposure. Mork should be undertaken in an isolated system such as a "glove-box". Employees should wash their hands and arms upon completion of the assigned task and before engaging in other activities not associated with the isolated system. Within regulated areas, the carcinogen should be stored in sealed containers, or enclosed in a closed system, including piping systems, with any sample ports or openings closed while the carcinogens are contained within. Open-vessel systems are prohibited. Each operation should be introduced in sufficient volume to maintain correct operation of the local exhaust system. For maintenance and decontamination activities, authorized employees entering the area should be provided with and required to wear clean, impervious garments, including gloves, boots and continuous-air supplied hood. Prior to removing protective garments the employee should undergo decontamination activities, authorized employees entering the area should be provided with and required to wear clean, impervious garments, including gloves, boots and continuous-air su
Personal protection	
Eye and face protection	 Safety glasses with side shields. Chemical goggles. Contact lenses may pose a special hazard; soft contact lenses may absorb and concentrate irritants. A written policy document, describing the wearing of lenses or restrictions on use, should be created for each workplace or task. This should include a review of lens absorption and adsorption for the class of chemicals in use and an account of injury experience. Medical and first-aid personnel should be trained in their removal and suitable equipment should be readily available. In the event of chemical exposure, begin eye irrigation immediately and remove contact lens as soon as practicable. Lens should be removed at the first signs of eye redness or irritation - lens should be removed in a clean environment only after workers have washed hands thoroughly. [CDC NIOSH Current Intelligence Bulletin 59], [AS/NZS 1336 or national equivalent]
Skin protection	See Hand protection below
Hands/feet protection	The selection of suitable gloves does not only depend on the material, but also on further marks of quality which vary from manufacturer to manufacturer. Where the chemical is a preparation of several substances, the resistance of the glove material can not be calculated in advance and has therefore to be checked prior to the application. The exact break through time for substances has to be obtained from the manufacturer of the protective gloves and has to be observed when

Biology and provide the activity of gover spin is activity activity and the spin intervent in the set of the spin intervent index of the sp		making a final choice.
Integrating and duration of contract. Integrating and duration of contract. Integrating and duration of given material, give thickness and duration of contract. give thickness and duration of the contract in the contract only contract and prove that a protection class of 5 or higher (freathinough time greater than 240 minute according to B 374, ASNE2 5161:10.10 or national equivalent) is economended. When only bird contract is expected, a glow with a protection class of 3 or higher (freathinough time greater than 240 minutes according to B 374, ASNE2 5161:10.10 or national equivalent) is economended. Some glove polymer types are less affected by movement and this should be taken into account when considering gloves for long-term second with the total through time - 400 min Good winh or beathinough time - 400 min Fair when breakthrough time - 400 min		
- demicial resistance of glove material, - development is resistance of glove material, - development is responsed to material, - development is responsed to make any court, is glowe with a protection data. - When protocols the expensed, a glowe with a protection data of the p		
Image: the second se		chemical resistance of glove material,
When protonged or frequently repeated contain may occur, a glow with a protection class of 5 or higher (preakthrough time greater than 240 minutes according to EN 374, ASNE2 512 5110.1 or national equivalent) is recommended. When only brief contact is expected, a glow with a protection class of 3 or higher (preakthrough time greater than 240 minutes according to EN 374, ASNE2 5110.1 or national equivalent) is recommended. Some glowe polymer types at less affected by movement and this should be taken into account when considering glowes for long-term use. Contaminated glowes should be replaced. Dow the glow use should be replaced. Some glowe polymer types at less affected by movement and this should be taken into account when considering glowes for long-term use. Contaminated glowes should be replaced. Some glowes at less affected by movement and this should be taken into account when considering glowes for long-term use. Contaminated glowes with a thickness bypically greater than 0.35 mm, are recommended. It is whole be emphasized that glowe that thickness is not necessarily a good predictor of glove resistance to a specific chemical, as the permeation afficiency of the glow will be dependent on the eact composition of the glow material. Therefore, glow selection should also be based on consideration of the task requirements and howelveg of or through terms, alway selection, the material efficiency of the glowe instance to a specific chemical, as the permeation afficiency of the glow will be required where a high degree of manual deative the search and the glow material there are applications, glowes are only likely to give a should be permeted to read. Thinker glowes (Up to 3 mm or tess) may be required where a high degree of manual deative the mean and the glowes are only likely to glowe and the duration precision and would normally be just for single use applications, the diogendeed of a non-perfumed motionary to there and would normally be part of using precision		
• When only bref contact is expected, a give with a protection class of 3 or higher (breakthrough time greater than 60 minutes according to EN 74, ASNE2 2101:10 r antialout equivalent) is account within considering gloves for long-term use. • Some glove polymer (types are less affected by movement and this should be taken into account when considering gloves for long-term use. • Some glove polymer (types are less affected by movement and this should be taken into account when considering gloves for long-term use. • Some glove polymer (types are less affected by movement and this should be taken into account when considering gloves for long-term use. • Constanting gloves should be replaced. • Born when glove material dispades • Four when glove material dispades • Pow when glove material dispades • Four when glove material dispades • Good when breakthrough time > 20 min • Born and the region of the dispades • Good when breakthrough time > 20 min • Born and account to ensure science on the ensure science on the dispade of the glove model. Therefore, the manufacturers technical tat should always be taken into account to ensure science of the ensure porticine dispade of the ensure of the ensure porticine dispade of the ensure of the ensure porticine dispade of the ensure science on the dispade of the ensure of the ensure porticine dispade of the ensure ensure on the dispade of the ensure		When prolonged or frequently repeated contact may occur, a glove with a protection class of 5 or higher (breakthrough time greater than 240
Contaminated gives should be replaced. As defined in AST F739-96 in any application, gives are rated as: - Excellent when breakthrough time > 400 min - Four when gives material against and gives are rated as: - Excellent when breakthrough time > 20 min - Four when gives material against For general applications, gives with a thickness typically greater than 0.35 mm, are recommended. For general applications, gives with a thickness typically greater than 0.35 mm, are recommended. For general applications, gives with a thickness typically greater than 0.35 mm, are recommended. For general applications, gives with a thickness typically greater than 0.35 mm, are recommended. For general applications, gives with a thickness typically greater than 0.35 mm, are recommended. For general applications, gives with a thickness typically greater than 0.35 mm, are recommended. For general applications, gives with a thickness typically greater than 0.35 mm, are recommended. For general applications, gives aware any gives and the gives model. Theoregives be taken into account to ensure stepsorphica gives of the take. Note: Depending on the activity being conducted, gives of the appropriate gives of the take. Note: Depending on the activity being conducted, gives of the attrivity is maded. However, these gives are any gives maintain any proteon on more imp by the give down and the gives models. For general application, gives are any gives maintain and the discover of the asset appropriate gives of the take. Note: Depending on the activity being conducted, gives and should be washed and dired throroughly. Application of a non-perfumed measure principal and the start evergreend when a high the dependent on the start evergreend when a high term starts are area asset. Body how beer For other protection below For other protection below For other prote		When only brief contact is expected, a glove with a protection class of 3 or higher (breakthrough time greater than 60 minutes according to EN
Excellent when breakthrough time > 480 min Good when breakthrough time > 20 min Fair when breakthrough time > 20 min For onernal applications, gloves with a thickness trypically greater than 0.35 mm, are recommended. It should be emphased that glove thickness is not necessarily a good predictor of glove resistance to a specific chemical, as the permeation efficiency of the glove will be dependent on the exact composition of the glove match. There on the case count one scare selection of the most appropriate glove for the task. Note: Depending on the activity being conducted, gloves of varying thickness may also exact more only may be regulated threa the site as the required when a when is a mechanical (as well as chemical) risk is. Where there is abrasion or Thinter gloves (down to 0.1 mm or leag) may be taken in the glove provided with the set as a chemical prior takes. For example: Thinter gloves (down to 0.1 mm or leag) may be play to single use applications, then disposed of. Thinter gloves more only may be required threa the site as a chemical prior takes. For example: Gloves should be examined for wear and; Gloves must be there is abrasion or Thinter glove only may be required when the set is a mechanical (as well as a chemical) risk is. Where abrasive particles are not present. Thinter glove only may be reguired when the set is a mechanical (as well as a chemical) risk is. Where abrasive particles are not present. Thinter glove wind well for marks as glove materials for protection against undissolved, dry solids, where abrasive particles are not p		· Contaminated gloves should be replaced.
Consideration Consideration Constrained Const		
• Poor when glove material degrades • Poor when glove material degrades • Progression applications, gloves with a thickness typically greater than 0.35 mm, are recommended. • It should be emphasised that glove thickness is not necessarily a good predictor of glove resistance to a specific chemical, as the permeation efficiency of the glove mile depender on the scat composition of the glove material. Therefore, glove self-ection should also be based on constatoration of the glove mile depender on the exact composition of the most appropriate glove for the task. • Clove thickness may also vary depending on the activity being onducted; gloves of varying thickness may be required for specific tasks. For example: • Thinner gloves (glove to 0.1 mm or less) may be required where a high degree of manual destority is needed. However, these gloves are only likely to gloves (glove to 3 mm or more) may be required where a high degree of manual destority is needed. However, these gloves are only likely to gloves (glove to 3 mm or more) may be required where a high degree of manual destority is needed. However, these gloves are only likely to gloves that duals on protection and would. • Thicker gloves (glo to 3 mm or more) may be required where a high degree of manual destority is needed. However, these gloves are only likely to glove material. • Body protection Body protection • Body upper cloves (glo to 3 mm or more) may be required where a splot degree of manual destority is needed. However, these gloves and gloves that the following polymers are suitable as glove material. • Dyperimeter • Dyperimolicity (Glove) • Body protectio		Good when breakthrough time > 20 min
For general applications, gives with a thickness typically greater than 0.35 mm, are recommended. It should be emphasised that gives thickness into a local predictor of gives resistance to a specific chemical, as the parmetion efficiency of the gives will be dependent on the exact composition of the give material. Therefore, gives selection should also be based on consideration of the task regularements and knowledge of breakthrough times. Givee thickness may also vary depending on the gives manufacturer, the gives the gives model. Therefore, the manufacturers technical data should always be taken into account to ensure selection of the most appropriate gives for the tasks. For example: Thinser gives (down to 0.1 mm or less) may be required where a high degree of manual detertity is needed. However, these gives are only likely to give short duration protection and would normally be just for single use applications, then disposed of. Thicker gives (down to 0.1 mm or less) may be required where there is a nechanical (as well as a chemical) risk i.e. where there is abrasion or puncture potential Gives must only be worn on dean hands. After using gives, hands should be washed and dried thoroughly. Application of a non-perfurned moisturiaer is recommended. Experience indicates that the following polymers are suitable as give materials for protection against undissolved, dry solids, where abrasive particles are not present. Polychindrogreene. Initine rubber. Houro caoucthouxo. Experience line datas in the following polymers are suitable as gives prior to entering. AlsNZS ISO 6529:2006 or national equivalent) Gives must which and for generations involving ca		
Other protection See Other protection Other protection See Other protection below		
Image: Control always be taken into account to ensure selection of the most appropriate glove for the task. Note: Depending on the activity being conducted, glowes of varying thickness may be required or specific tasks. For example: Thinner gloves (down to 0.1 mm or less) may be required where a high degree of manual dexterity is needed. However, these gloves are only likely to give short duration protection and would normally be just for single use applications, then disposed of. Thicker gloves (up to 3 mm or more) may be required where a high degree of manual dexterity is needed. However, these gloves are only nucleur potential Gloves must only be worn on clean hands. After using gloves, hands should be washed and dried thoroughly. Application of a non-perfumed moisturiser is recommended. Experience indicates that the following polymers are suitable as glove materials for protection against undissolved, dry solids, where abrasive particles are not present. I hulfv tubber. hulfv tubber. I hulfv tubber. hulfv tubber. I hulfv tubber. bulfvi tubber. I hulfvi tubber. b		efficiency of the glove will be dependent on the exact composition of the glove material. Therefore, glove selection should also be based on
• Thinner gloves (down to 0.1 mm or less) may be required where a high degree of manual dexterity is needed. However, these gloves are only likely to give short duration protection and would normally be just for single use applications, then disposed of. • Thicker gloves (up to 3 mm or more) may be required where there is a mechanical (as well as a chemical) risk i.e. where there is abrasion or puncture potential Gloves must only be worn on clean hands. After using gloves, hands should be washed and dried thoroughly. Application of a non-perfumed moisturiser is recommended. Experience indicates that the following polymers are suitable as glove materials for protection against undissolved, dry solids, where abrasive particles are not present. • bylycholomprene. • initrie rubber. • buyly rubber. • buyle conceautchouse. • polyvinyl choride. Gloves should be examined for wear and/ or degradation constantly. Body protection See Other protection below • Employees working with confirmed human carcinogens should be provided with, and required to wear and use half-face filter-type respirator affording higher levelse of proteclive or anizonal equivalent] <th></th> <th>data should always be taken into account to ensure selection of the most appropriate glove for the task.</th>		data should always be taken into account to ensure selection of the most appropriate glove for the task.
Ikely to give short duration protection and would normally be just or single use applications, then disposed of. Thicker gloves (up to 3 mm or more) may be required where there is a mechanical (as well as a chemical) risk i.e. where there is abrasion or puncture potential Gloves must only be worn on clean hands. After using gloves, hands should be washed and dried thoroughly. Application of a non-perfumed moisturiser is recommended. Experience indicates that the following polymers are suitable as glove materials for protection against undissolved, dry solids, where abrasive particles are not present. polychioroprene. hintine rubber. buyly inbber. buyly inbber. buyly inbber. buyly inbber. buyly inbber. buyly inber. buyly inber. buyle incoreaucthoue. boyleying chloride. Body protection See Other protection below Other protection below Employees engaged in handing operations involving carcinogens should be provided with, and required to wear, clean, full body protective clothing (smocks, coveralls, or long-sleeved shirt and pants), shoe covers and gloves prior to entering the regulated area. [AS/NZ5 ISO 6529:2006 or national equivalent] Employees engaged in handing operations involving carcinogens should be provided with, and required to wear and use half-face filter-type reginators with lifters for dusts, maiss and fumes, or air purfying canisters or cartridges. A respirator affording higher levels of protection may be substituted. [AS/NZ5 1715 or national equivalent] Employees showers and eyewash fountains, supplied w		
Other protection 		
Gloves must only be worn on clean hands. After using gloves, hands should be washed and dried thoroughly. Application of a non-perfumed moisturiser is recommended. Experience indicates that the following polymers are suitable as glove materials for protection against undissolved, dry solids, where abrasive particles are not present. • hitrile rubber. • buly inubber. • buly inubber. • buly inubber. • logical control • Body protection Body protection See Other protection below * Employees working with confirmed human carcinogens should be provided with, and be required to wear, clean, full body protective clothing (smocks, coveralls, or long-sleeved shift and pants), shoe covers and gloves prior to entering the regulated area. [AS/NZS ISO 6529:2006 or national equivalent] • Employees working with confirmed human carcinogens should be provided with, and required to wear and use half-face filter-type respirators with filters for dusts, mists and fumes, or air purfying canisters or cartridges. A respirator affording higher levels of protection may be substituted. (AS/NZS 1175 to rational equivalent] • Emergency deluge showers and evexash fountains, supplied with potable water, should be located near, within sight of, and on the same level with locations where direct exposure is likely. • Prior to each exit from an area containing confirmed human carcinogens, employees should be required to remove and leave protective clothing and equipment at the point of exit and at the late st of the day, to place used dorhing and equipment in impervious containers must be identifie		
Experience indicates that the following polymers are suitable as glove materials for protection against undissolved, dry solids, where abrasive particles are not present. polychioroprene. nitrile nubber. fluorocaoutchouc. polyrily chloride. Gloves should be examined for wear and/ or degradation constantly. Body protection See Other protection below Employees or long-sleeved shirt and pants), shoe covers and gloves prior to entering the regulated area. [AS/NZS ISO 6529:2006 or national equivalent] Employees engaged in handling operations involving carcinogens should be provided with, and required to wear and use half-face filter-type respirators with filters for dusts, mists and fumes, or air purifying canisters or cartridges. A respirator affording higher levels of protection may be substituted. [AS/NZS IYO 6529:2006 or national equivalent] Employees engaged in handling operations involving carcinogens should be provided with, and required to wear and use half-face filter-type respirators with filters for dusts, mists and fumes, or air purifying canisters or cartridges. A respirator affording higher levels of protection may be substituted. [AS/NZS IY15 or national equivalent] Emergency deluge showers and eyewash fountains, supplied with potable water, should be located near, within sight of, and on the same level with focations where direct exposure is likely. Prior to each exit from an area containing confirmed human carcinogens, employees enbud be provided with and required to wear each and the point of exit and at the last exit of the day, to place used clothing and equipment in impervious containers must be identified with suitable tabels. For maintenance and decontamination architoge soluchingrovious containers must be identified with suitable tabels. Fo		
particles are not present. > polychioroprene. > butyl rubber. > butyl rubber. > butyl rubber. > butyl rubber. > polychioroprene. > filtorocaoutchouc. > polychiory choirde. Gloves should be examined for wear and/ or degradation constantly. Body protection See Other protection below Employees working with confirmed human carcinogens should be provided with, and be required to wear, clean, full body protective clothing (smocks, coveralls, or long-sleeved shirt and pants), shoe covers and gloves prior to entering the regulated area. [AS/NZS ISO 6529:2006 or national equivalent] Employees engaged in handling operations involving carcinogens should be provided with, and required to wear and use half-face filter-type respirators with filters for dusts, mists and fumes, or air purifying canisters or catridges. A respirator affording higher levels of protection may be substituted. [AS/NZS 1715 or national equivalent] Emergency deluge showers and equivalent] Emergency deluge showeres of decontamination or disposal. The contents of such impervious containers at the point of exit for purposes of decontamination activities, authorized employees entaining and equiverent in impervious containers at the point of exit for purposes of decontamination on disposal. The contents of such impervious gament in impervious containers at the point of exit for purposes of decontamination activities, authorized employees entaining the area should be provided with and required to wear clean, impervious		
• polychloroprene. • hitrile rubber. • butyf rubber. • fluorocaoutchouc. • polyvingt holinoide. Gloves should be examined for wear and/ or degradation constantly. Body protection See Other protection below Employees working with confirmed human carcinogens should be provided with, and be required to wear, clean, full body protective clothing (smocks, coveralls, or long-sleeved shirt and pants), shoe covers and gloves prior to entering the regulated area. [AS/NZS 1SO 6529:2006 or national equivalent] Employees working with confirmed human carcinogens should be provided with, and required to wear and use half-face filter-type respirators with filters for dusts, mists and fumes, or air purifying canisters or cartridges. A respirator affording higher levels of protection may be substituted. [AS/NZS 1715 or national equivalent] Employees where direct exposure is likely. Prior to each exit from an area containing confirmed human carcinogens, employees should be located near, within sight of, and on the same level with hocations where direct exposure is likely. Prior to each exit from an area containing confirmed human carcinogens, employees should be provided with and required to wear on all eave protective clothing and equipment at the point of exit and at the last exit of the day, to place used clothing and equipment is intervious containers at the point of exit for purposes of decontamination activities, authorized employees entering the area should be provided with and required to wear each and inpreprivous garments, including gloves, boots and continuous-air sus		
• butyl rubber: • hutyl rubber: • fluorocaoutchouc: • polyvinyl chloride. Gloves should be examined for wear and/ or degradation constantly. Body protection See Other protection below Image: See Other protection below • Employees working with confirmed human carcinogens should be provided with, and be required to wear, clean, full body protective clothing (smocks, coveralls, or long-sleeved shirt and pants), shoe covers and gloves prior to entering the regulated area. [AS/NZS ISO 6529:2006 or national equivalent] • Employees engaged in handling operations involving carcinogens should be provided with, and required to wear and use half-face filter-type respirators with filters for dusts, mists and fumes, or air purifying canisters or cartridges. A respirator affording higher levels of protection may be substituted. [AS/NZS 1715 or national equivalent] • Emergency deluge showers and eyewash fountains, supplied with potable water, should be located near, within sight of, and on the same level with locations where direct exposure is likely. • Prior to each exit form an area contamination or disposal. The contents of such impervious containers must be identified with suitable labels. For maintenance and decontamination or disposal. The contents of such impervious containers moval be inverse and hood. • Overalls. • Prior to eraon. • Skin cleansing cream. • Skin cleansing cream.		
Image: Interpretation Image: Interpretation of the search of the sea		
Gloves should be examined for wear and/ or degradation constantly. Body protection See Other protection below Image: the protection below Employees working with confirmed human carcinogens should be provided with, and be required to wear, clean, full body protective clothing (smocks, coveralls, or long-sleeved shirt and pants), shoe covers and gloves prior to entering the regulated area. [AS/NZS ISO 6529:2006 or national equivalent] Image: the protection below 		
Body protection See Other protection below 		
 Contempose working with confirmed human carcinogens should be provided with, and be required to wear, clean, full body protective clothing (smocks, coveralls, or long-sleeved shirt and pants), shoe covers and gloves prior to entering the regulated area. [AS/NZS ISO 6529:2006 or national equivalent] Employees engaged in handling operations involving carcinogens should be provided with, and required to wear and use half-face filter-type respirators with filters for dusts, mists and fumes, or air purifying canisters or cartridges. A respirator affording higher levels of protection may be substituted. [AS/NZS 1715 or national equivalent] Emergency deluge showers and eyewash fountains, supplied with potable water, should be located near, within sight of, and on the same level with locations where direct exposure is likely. Prior to each exit from an area containing confirmed human carcinogens, employees should be required to remove and leave protective clothing and equipment at the point of exit and at the last exit of the day, to place used clothing and equipment in impervious containers at the point of exit for purposes of decontamination or disposal. The contents of such impervious containers must be identified with suitable labels. For maintenance and decontamination activities, authorized employees entering the area should be provided with and required to wear impervious garments, including gloves, boots and continuous-air supplied hood. Prior to removing protective garments the employee should undergo decontamination and be required to shower upon removal of the garments and hood. Overalls. P.V.C apron. Barrier cream. Skin cleansing cream. 	Pody protection	
 (smocks, coveralls, or long-sleeved shirt and pants), shoe covers and gloves prior to entering the regulated area. [AS/NZS ISO 6529:2006 or national equivalent] Employees engaged in handling operations involving carcinogens should be provided with, and required to wear and use half-face filter-type respirators with filters for dusts, mists and fumes, or air purifying canisters or cartridges. A respirator affording higher levels of protection may be substituted. [AS/NZS 1715 or national equivalent] Emergency deluge showers and eyewash fountains, supplied with potable water, should be located near, within sight of, and on the same level with locations where direct exposure is likely. Prior to each exit from an area containing confirmed human carcinogens, employees should be required to remove and leave protective clothing and equipment at the point of exit and at the last exit of the day, to place used clothing and equipment in impervious containers at the point of exit for purposes of decontamination or disposal. The contents of such impervious containers must be identified with suitable labels. For maintenance and decontamination activities, authorized employees entering the area should be provided with and required to wear clean, impervious garments, including gloves, boots and continuous-air supplied hood. Prior to removing protective garments the employee should undergo decontamination and be required to shower upon removal of the garments and hood. Overalls. P.V.C apron. Barrier cream. Skin cleansing cream. 	Body protection	
Other protection level with locations where direct exposure is likely. Prior to each exit from an area containing confirmed human carcinogens, employees should be required to remove and leave protective clothing and equipment at the point of exit and at the last exit of the day, to place used clothing and equipment in impervious containers at the point of exit for purposes of decontamination or disposal. The contents of such impervious containers must be identified with suitable labels. For maintenance and decontamination activities, authorized employees entering the area should be provided with and required to wear clean, impervious garments, including gloves, boots and continuous-air supplied hood. Prior to removing protective garments the employee should undergo decontamination and be required to shower upon removal of the garments and hood. Overalls. P.V.C apron. Barrier cream. Skin cleansing cream.		 (smocks, coveralls, or long-sleeved shirt and pants), shoe covers and gloves prior to entering the regulated area. [AS/NZS ISO 6529:2006 or national equivalent] Employees engaged in handling operations involving carcinogens should be provided with, and required to wear and use half-face filter-type respirators with filters for dusts, mists and fumes, or air purifying canisters or cartridges. A respirator affording higher levels of protection may
Other protection Prior to each exit from an area containing confirmed human carcinogens, employees should be required to remove and leave protective clothing and equipment at the point of exit and at the last exit of the day, to place used clothing and equipment in impervious containers at the point of exit for purposes of decontamination or disposal. The contents of such impervious containers must be identified with suitable labels. For maintenance and decontamination activities, authorized employees entering the area should be provided with and required to wear clean, impervious garments, including gloves, boots and continuous-air supplied hood. Prior to removing protective garments the employee should undergo decontamination and be required to shower upon removal of the garments and hood. Overalls. P.V.C apron. Barrier cream. Skin cleansing cream. 		
Other protection clothing and equipment at the point of exit and at the last exit of the day, to place used clothing and equipment in impervious containers at the point of exit for purposes of decontamination or disposal. The contents of such impervious containers must be identified with suitable labels. For maintenance and decontamination activities, authorized employees entering the area should be provided with and required to wear clean, impervious garments, including gloves, boots and continuous-air supplied hood. Prior to removing protective garments the employee should undergo decontamination and be required to shower upon removal of the garments and hood. Overalls. P.V.C apron. Barrier cream. Skin cleansing cream.		
 In the point of exit for purposes to decontamination of usposal. The contents of such impervious containers must be identified with suitable labels. For maintenance and decontamination activities, authorized employees entering the area should be provided with and required to wear clean, impervious garments, including gloves, boots and continuous-air supplied hood. Prior to removing protective garments the employee should undergo decontamination and be required to shower upon removal of the garments and hood. Overalls. P.V.C apron. Barrier cream. Skin cleansing cream. 	Other protection	clothing and equipment at the point of exit and at the last exit of the day, to place used clothing and equipment in impervious containers at
 Prior to removing protective garments the employee should undergo decontamination and be required to shower upon removal of the garments and hood. Overalls. P.V.C apron. Barrier cream. Skin cleansing cream. 		labels. For maintenance and decontamination activities, authorized employees entering the area should be provided with and required to
 Overalls. P.V.C apron. Barrier cream. Skin cleansing cream. 		Prior to removing protective garments the employee should undergo decontamination and be required to shower upon removal of the
 P.V.C apron. Barrier cream. Skin cleansing cream. 		
Skin cleansing cream.		► P.V.C apron.

Respiratory protection

Particulate. (AS/NZS 1716 & 1715, EN 143:2000 & 149:001, ANSI Z88 or national equivalent)

Required Minimum Protection Factor	Half-Face Respirator	Full-Face Respirator	Powered Air Respirator
up to 10 x ES	P1 Air-line*	-	PAPR-P1 -
up to 50 x ES	Air-line**	P2	PAPR-P2
up to 100 x ES	-	P3	-
		Air-line*	-
100+ x ES	-	Air-line**	PAPR-P3

* - Negative pressure demand ** - Continuous flow

A(AII classes) = Organic vapours, B AUS or B1 = Acid gasses, B2 = Acid gas or hydrogen cyanide(HCN), B3 = Acid gas or hydrogen cyanide(HCN), E = Sulfur dioxide(SO2), G = Agricultural chemicals, K = Ammonia(NH3), Hg = Mercury, NO = Oxides of nitrogen, MB = Methyl bromide, AX = Low boiling point organic compounds(below 65 degC)

 \cdot Respirators may be necessary when engineering and administrative controls do not adequately prevent exposures.

The decision to use respiratory protection should be based on professional judgment that takes into account toxicity information, exposure measurement data, and frequency and likelihood of the worker's exposure - ensure users are not subject to high thermal loads which may result in heat stress or distress due to personal protective equipment (powered, positive flow, full face apparatus may be an option).
 Published occupational exposure limits, where they exist, will assist in determining the adequacy of the selected respiratory protection. These may be government mandated or

 Published occupational exposure limits, where they exist, will assist in determining the adequacy of the selected respiratory protection. These may be government mandated o vendor recommended.

Certified respirators will be useful for protecting workers from inhalation of particulates when properly selected and fit tested as part of a complete respiratory protection program.
 Where protection from nuisance levels of dusts are desired, use type N95 (US) or type P1 (EN143) dust masks. Use respirators and components tested and approved under

appropriate government standards such as NIOSH (US) or CEN (EU)

 \cdot Use approved positive flow mask if significant quantities of dust becomes airborne.

· Try to avoid creating dust conditions.

Where significant concentrations of the material are likely to enter the breathing zone, a Class P3 respirator may be required.

Class P3 particulate filters are used for protection against highly toxic or highly irritant particulates.

Filtration rate: Filters at least 99.95% of airborne particles

Suitable for:

· Relatively small particles generated by mechanical processes eg. grinding, cutting, sanding, drilling, sawing.

 \cdot Sub-micron thermally generated particles e.g. welding fumes, fertilizer and bushfire smoke.

· Biologically active airborne particles under specified infection control applications e.g. viruses, bacteria, COVID-19, SARS

 \cdot Highly toxic particles e.g. Organophosphate Insecticides, Radionuclides, Asbestos

Note: P3 Rating can only be achieved when used with a Full Face Respirator or Powered Air-Purifying Respirator (PAPR). If used with any other respirator, it will only provide filtration protection up to a P2 rating.

SECTION 9 Physical and chemical properties

Information on basic physical and chemical properties

Appearance	Stone surface, immiscible in water.		
Physical state	Solid	Relative density (Water = 1)	1.5-2.7
Odour	Not Available	Partition coefficient n-octanol / water	Not Available
Odour threshold	Not Available	Auto-ignition temperature (°C)	Not Available
pH (as supplied)	Not Applicable	Decomposition temperature (°C)	Not Available
Melting point / freezing point (°C)	Not Available	Viscosity (cSt)	Not Available
Initial boiling point and boiling range (°C)	Not Available	Molecular weight (g/mol)	Not Applicable
Flash point (°C)	Not Available	Taste	Not Available
Evaporation rate	Not Available	Explosive properties	Not Available
Flammability	Not Available	Oxidising properties	Not Available
Upper Explosive Limit (%)	Not Available	Surface Tension (dyn/cm or mN/m)	Not Applicable
Lower Explosive Limit (%)	Not Available	Volatile Component (%vol)	Not Available
Vapour pressure (kPa)	Not Available	Gas group	Not Available
Solubility in water	Immiscible	pH as a solution (Not Available%)	Not Applicable
Vapour density (Air = 1)	Not Available	VOC g/L	Not Available

SECTION 10 Stability and reactivity

Reactivity	See section 7
Chemical stability	 Unstable in the presence of incompatible materials. Product is considered stable. Hazardous polymerisation will not occur.
Possibility of hazardous reactions	See section 7
Conditions to avoid	See section 7
Incompatible materials	See section 7
Hazardous decomposition products	See section 5

SECTION 11 Toxicological information

Information on toxicological effects

Inhaled	The material can cause respiratory irritation in some persons. The body's response to such irritation can cause further lung damage. Inhalation of vapours may cause drowsiness and dizziness. This may be accompanied by sleepiness, reduced alertness, loss of reflexes, lack of co-ordination, and vertigo. Persons with impaired respiratory function, airway diseases and conditions such as emphysema or chronic bronchitis, may incur further disability if excessive concentrations of particulate are inhaled. If prior damage to the circulatory or nervous systems has occurred or if kidney damage has been sustained, proper screenings should be conducted on individuals who may be exposed to further risk if handling and use of the material result in excessive exposures. Not normally a hazard due to non-volatile nature of product
Ingestion	The material has NOT been classified by EC Directives or other classification systems as "harmful by ingestion". This is because of the lack of corroborating animal or human evidence.
Skin Contact	The material may cause moderate inflammation of the skin either following direct contact or after a delay of some time. Repeated exposure can cause contact dermatitis which is characterised by redness, swelling and blistering. Skin contact is not thought to have harmful health effects (as classified under EC Directives); the material may still produce health damage following entry through wounds, lesions or abrasions. Open cuts, abraded or irritated skin should not be exposed to this material

Eye	There is evidence that material may produce eye irritation inflammation may be expected with pain.	on in some persons and produce eye damage 24 hours or more after instillation. Sev		
Chronic	Long-term exposure to respiratory irritants may result in airways disease, involving difficulty breathing and related whole-body problems. There is sufficient evidence to suggest that this material directly causes cancer in humans. Substance accumulation, in the human body, may occur and may cause some concern following repeated or long-term occupational exposure.			
Limestone - Natural stone	ΤΟΧΙΟΙΤΥ	IRRITATION		
slabs or tiles	Not Available	Not Available		
	ΤΟΧΙΟΙΤΥ	IRRITATION		
	dermal (rat) LD50: >2000 mg/kg ^[1]	Eye (rabbit): 0.75 mg/24h - SEVERE		
calcium carbonate	Inhalation(Rat) LC50; >3 mg/l4h ^[1]	Eye: no adverse effect observed (not irritating) ^[1]		
	Oral (Rat) LD50; >2000 mg/kg ^[1]	Skin (rabbit): 500 mg/24h-moderate		
	Skin: no adverse effect observed (not irritating) ^[1]			
	ΤΟΧΙΟΙΤΥ	IRRITATION		
silica crystalline - quartz	Oral (Rat) LD50; 500 mg/kg ^[2]	Not Available		
Legend:	1 Value obtained from Europe ECHA Registered Subs	ances - Acute toxicity 2.* Value obtained from manufacturer's SDS. Unless otherwis		

CALCIUM CARBONATE	No evidence of carcinogenic properties. No evidence of mutagenic or teratogenic effects. Asthma-like symptoms may continue for months or even years after exposure to the material ends. This may be due to a non-allergic condition known as reactive airways dysfunction syndrome (RADS) which can occur after exposure to high levels of highly irritating compound. Main criteria for diagnosing RADS include the absence of previous airways disease in a non-atopic individual, with sudden onset of persistent asthma-like symptoms within minutes to hours of a documented exposure to the irritant. Other criteria for diagnosis of RADS include a reversible airflow pattern on lung function tests, moderate to severe bronchial hyperreactivity on methacholine challenge testing, and the lack of minimal lymphocytic inflammation, without eosinophila. RADS (or asthma) following an irritating inhalation is an infrequent disorder with rates related to the concentration of and duration of exposure to the irritating substance. On the other hand, industrial bronchitis is a disorder that occurs as a result of exposure due to high concentrations of irritating substance (often particles) and is completely reversible after exposure ceases. The disorder is characterized by difficulty breathing, cough and mucus production. The material may produce severe irritation to the eye causing pronounced inflammation. Repeated or prolonged exposure to irritants may produce conjunctivitis.
SILICA CRYSTALLINE - QUARTZ	 WARNING: For inhalation exposure <u>ONLY</u>: This substance has been classified by the IARC as Group 1: CARCINOGENIC TO HUMANS The International Agency for Research on Cancer (IARC) has classified occupational exposures to respirable (<5 um) crystalline silica as being carcinogenic to humans . This classification is based on what IARC considered sufficient evidence from epidemiological studies of humans for the carcinogenicity of inhaled silica in the forms of quartz and cristobalite. Crystalline silica is also known to cause silicosis, a non-cancerous lung disease. Intermittent exposure produces; focal fibrosis, (pneumoconiosis), cough, dyspnoea, liver tumours. * Millions of particles per cubic foot (based on impinger samples counted by light field techniques). NOTE : the physical nature of quartz in the product determines whether it is likely to present a chronic health problem. To be a hazard the material must enter the breathing zone as respirable particles.

Acute Toxicity	×	Carcinogenicity	×
Skin Irritation/Corrosion	×	Reproductivity	×
Serious Eye Damage/Irritation	×	STOT - Single Exposure	×
Respiratory or Skin sensitisation	×	STOT - Repeated Exposure	×
Mutagenicity	×	Aspiration Hazard	×
		Legend: 🗙 – Data either n	not available or does not fill the criteria for classification

SECTION 12 Ecological information

xicity Limestone - Natural stone slabs or tiles	Endpoint	Test Duration (hr)	Species	Value	Source
	Not Available	Not Available	Not Available	Not Available	Not Available
calcium carbonate	Endpoint	Test Duration (hr)	Species	Value	Source
	NOEC(ECx)	1h	Fish	4-320mg/l	4
	EC50	72h	Algae or other aquatic plants	>14mg/l	2
	LC50	96h	Fish	>165200mg/L	4

	Endpoint	Test Duration (hr)	Species	Value	Source
silica crystalline - quartz	Not Available	Not Available	Not Available	Not Available	Not Available
Legend:	Extracted from 1. IUCLID Toxicity Data 2. Europe ECHA Registered Substances - Ecotoxicological Information - Aquatic Toxicity 4. US EPA, Ecotox database - Aquatic Toxicity Data 5. ECETOC Aquatic Hazard Assessment Data 6. NITE (Japan) - Bioconcentration Data 7. METI (Japan) - Bioconcentration Data 8. Vendor Data				

DO NOT discharge into sewer or waterways.

Persistence and degradability

Ingredient	Persistence: Water/Soil	Persistence: Air	
	No Data available for all ingredients	No Data available for all ingredients	
Bioaccumulative pote	ential		
Ingredient	Bioaccumulation		
	No Data available for all ingredients		
Mobility in soil			
Ingredient	Mobility		
	No Data available for all ingredients		

SECTION 13 Disposal considerations

/aste treatment methods Product / Packaging disposal	 Containers may still present a chemical hazard/ danger when empty. Return to supplier for reuse/ recycling if possible. Otherwise: If container can not be cleaned sufficiently well to ensure that residuals do not remain or if the container cannot be used to store the same product, then puncture containers, to prevent re-use, and bury at an authorised landfill. Where possible retain label warnings and SDS and observe all notices pertaining to the product. DO NOT allow wash water from cleaning or process equipment to enter drains. It may be necessary to collect all wash water for treatment before disposal. In all cases disposal to sever may be subject to local laws and regulations and these should be considered first. Where in doubt contact the responsible authority. Recycle wherever possible or consult manufacturer for recycling options. Consult State Land Waste Management Authority for disposal. Bury residue in an authorised landfill. Recycle containers if possible, or dispose of in an authorised landfill.
---	---

SECTION 14 Transport information

Labels Required		
Marine Pollutant	NO	
HAZCHEM	Not Applicable	

Land transport (ADG): NOT REGULATED FOR TRANSPORT OF DANGEROUS GOODS

Air transport (ICAO-IATA / DGR): NOT REGULATED FOR TRANSPORT OF DANGEROUS GOODS

Sea transport (IMDG-Code / GGVSee): NOT REGULATED FOR TRANSPORT OF DANGEROUS GOODS

Transport in bulk according to Annex II of MARPOL and the IBC code Not Applicable

Transport in bulk in accordance with MARPOL Annex V and the IMSBC Code

Product name	Group
calcium carbonate	Not Available
silica crystalline - quartz	Not Available

Transport in bulk in accordance with the ICG Code

Product name	Ship Type
calcium carbonate	Not Available
silica crystalline - quartz	Not Available

SECTION 15 Regulatory information

Safety, health and environmental regulations / legislation specific for the substance or mixture

calcium carbonate is found on the following regulatory lists

Australian Inventory of Industrial Chemicals (AIIC)

International WHO List of Proposed Occupational Exposure Limit (OEL) Values for Manufactured Nanomaterials (MNMS)

silica crystalline - quartz is found on the following regulatory lists

Australia Hazardous Chemical Information System (HCIS) - Hazardous Chemicals Australia Model Work Health and Safety Regulations - Hazardous chemicals (other than lead) requiring health monitoring

Australian Inventory of Industrial Chemicals (AIIC)

Chemical Footprint Project - Chemicals of High Concern List

International Agency for Research on Cancer (IARC) - Agents Classified by the IARC Monographs

International Agency for Research on Cancer (IARC) - Agents Classified by the IARC Monographs - Group 1: Carcinogenic to humans

National Inventory Status

National Inventory	Status	
Australia - AIIC / Australia Non-Industrial Use	Yes	
Canada - DSL	Yes	
Canada - NDSL	No (silica crystalline - quartz)	
China - IECSC	Yes	
Europe - EINEC / ELINCS / NLP	Yes	
Japan - ENCS	Yes	
Korea - KECI	Yes	
New Zealand - NZIoC	Yes	
Philippines - PICCS	Yes	
USA - TSCA	Yes	
Taiwan - TCSI	Yes	
Mexico - INSQ	Yes	
Vietnam - NCI	Yes	
Russia - FBEPH	Yes	
Legend:	Yes = All CAS declared ingredients are on the inventory No = One or more of the CAS listed ingredients are not on the inventory. These ingredients may be exempt or will require registration.	

SECTION 16 Other information

Revision Date	22/07/2022
Initial Date	22/07/2022

Other information

Classification of the preparation and its individual components has drawn on official and authoritative sources as well as independent review by the Chemwatch Classification committee using available literature references.

The SDS is a Hazard Communication tool and should be used to assist in the Risk Assessment. Many factors determine whether the reported Hazards are Risks in the workplace or other settings. Risks may be determined by reference to Exposures Scenarios. Scale of use, frequency of use and current or available engineering controls must be considered.

Definitions and abbreviations

PC-TWA: Permissible Concentration-Time Weighted Average PC-STEL: Permissible Concentration-Short Term Exposure Limit IARC: International Agency for Research on Cancer ACGIH: American Conference of Governmental Industrial Hygienists STEL: Short Term Exposure Limit TEEL: Temporary Emergency Exposure Limit. IDLH: Immediately Dangerous to Life or Health Concentrations ES: Exposure Standard OSF: Odour Safety Factor NOAEL :No Observed Adverse Effect Level LOAEL: Lowest Observed Adverse Effect Level TLV: Threshold Limit Value LOD: Limit Of Detection OTV: Odour Threshold Value **BCF: BioConcentration Factors** BEI: Biological Exposure Index AIIC: Australian Inventory of Industrial Chemicals DSL: Domestic Substances List NDSL: Non-Domestic Substances List IECSC: Inventory of Existing Chemical Substance in China EINECS: European INventory of Existing Commercial chemical Substances ELINCS: European List of Notified Chemical Substances NLP: No-Longer Polymers ENCS: Existing and New Chemical Substances Inventory KECI: Korea Existing Chemicals Inventory NZIoC: New Zealand Inventory of Chemicals PICCS: Philippine Inventory of Chemicals and Chemical Substances TSCA: Toxic Substances Control Act TCSI: Taiwan Chemical Substance Inventory INSQ: Inventario Nacional de Sustancias Químicas NCI: National Chemical Inventory FBEPH: Russian Register of Potentially Hazardous Chemical and Biological Substances

This document is copyright.

Apart from any fair dealing for the purposes of private study, research, review or criticism, as permitted under the Copyright Act, no part may be reproduced by any process without written permission from CHEMWATCH.

TEL (+61 3) 9572 4700.